



Sanitary Sewer Overflow Annual Report

Division of Surface Water

Date: 02/20/20
Facility name: LeSourdsville Regional WRF
Ohio NPDES permit no.: 1PK00011*ND
Period covered by report: January 1, 2019 to December 31, 2019


Contact person

Name: Todd Madden
Title: LES Chief Operator
Mailing address: 130 High Street, Hamilton, OH 45011
Telephone: (513)887 - 5551
Email: Todd.Madden@bcOhio.us

Certification:

I certify under penalty of law that I have personally examined and am familiar with the information in this report and all attachments. Based on my inquiry of those persons immediately for obtaining the information contained in the report, I believe that the information is true, accurate, and complete.

Name Todd Madden **Title:** LES Chief Operator
(typed):

Signature:  **Date:** 2/26/2020

Enter narrative analysis of WIB patterns by location, frequency and cause.

Headgates Manor -- both instances were due to contractor error. One occasion allowed 2 WIB's due to tangled floats and batteries dead on the backup pump. The other occasion caused 2 WIB's that were due to the bypass pump being frozen

Windsor Estates -- discovered that contractor had started a new section and did not install a plug in manhole

Monroe 18-3-3 -- WIB caused by grease blockage. This is on quarterly cleaning schedule and had been cleaned 24 days prior to WIB report